





Report No.: AJFTS25006286R01 Date: Apr 28,2025 Page 1 of 27

SEDNA (HOLDINGS) LTD

7/F., DAWNING HOUSE, 145 CONNAUGHT ROAD CENTRAL, SHEUNG WAN, HONG ROAD

Sample Description : STEEL MAPERIAL FIREPROOF DOOR

Color : GREY

Thickness : 20mm

Composition STEEL

Luyer : SEDNA (HOLDINGS) LTD

The above sample is data and information was / were submitted

It responsible for the authenticity interval conclusion a sing therefrom. Results apply to the sample as received.

le Receiving Date: Jan 16,2025

sting Period Jan 16,2025 to Feb 10,2025

**Test Required** EN 1634-1:2014+A1:2018 Fire resistance and smoke control tests for door and

> shutter assemblies, openable windows and elements of building hardware, Part 1: Fire resistance test for door and shutter assemblies and openable

windows.

Test result(s) See attached sheet

Signed for and on behalf of

www.securitysteeldoor.com www.security

MMM.Sec



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443



**Test Report** 

Report No.: AJFTS25000286R01 Date: Apr 28,2025 Page 2 of 27

## Introduction

To determine the fire resistance performance of single leaf steel fire door with vision panel when tested in accordance with FN 1634-1:2014+A1:2018.

specimen was exposed to a time-temperature to ve as dictated by the clause 5.1 of EN 1363-beriod of 121min. conducted on FEB.10, 2025. 1:2020 for a period of 121min.

The lest was conducted on FEB.10, 2025.

## 7 Test Specimen

installed on FEB.10, 2025.

e fire door specimen was received on IAN. 16, 2025, and was stored in the laboratory until FEB 18 During the storage of the specimen, the temperature and humidity of the laboratory were measured and recorded as being within a range of from 10°C to 15°C and 41% to 68% respectively. The checimen was

According to the drawings and information provided by client and the measurement on the scene, the structure of single leaf steel fire door with vision panel specimen was as follows:

Door frame: The overall dimensions were 1140mm wide by 2105mm high by 105mm deep, the clear size was 1040mm wide by 2035mm high, it was made of 1.5mm thick galvanized steel plate.

Jo board ft.

J + Mgo board + L

Kness of 62mm. Four h

Jas installed at 1000mm from th.

Jas et 200mm wide by 600mm high wa

Jac see Light 1 of the structural drawing of the specified downess mounted within apertures provided within a m.

Jeaf applied away from the heating conditions of the test

The tool gaps were measured before the test as shown in Figure 2 Door leaf: The overall dimensions were 995mm wide by 2007mm high by 62mm thick. The interior of the door leaf was filled with pearlite and Mgo board for heat insulation. The main structure of the door leaf was 0.8mm thick galvanized steel plate + Mgo board + pearlite + 0.8mm thick galvanized steel plate from the exposed face, with a total thickness of 62mm. Four hinges were installed at one side of the door leaf, and a #918902 type fire lock was installed at 1000mm from the bottom of the door leaf on the other side. A vision panel with dimensions 200mm wide by 600mm high was installed next to the fire lock, with a distance of

For details see Figure 1 of the structural drawing of the specimen provided by the client.

The fire does was mounted within apertures provided within a masonry wall construction such that the door

检验检测专用章

Unless otherwise agreed in writing, this document is issued by the Company subject tows General Conditionavailable on request or accessible at https://www.ags.com/enr/ferms-and-standlons, Attention is indemnification and jurisdiction issues defined therein. Any holder of this accessible is advised the Company's findings at the time of its Intervention only and withinkines bits of Clientary asponsibility is to its Client and this document does not exponent be gate to a transmit of the transaction documents. This document cannot be reproduct to a transmit or a characteristic of the content or apply are retained for 30 days only. Intion: To check the authenticity of testing finspermant. Our Doccheckes accommended to the content of apply that is a content of apply that



COLU

TEST REPORT



Unexposed face of the specimen (After test duration of 120min)



Unexposed face of the specimen (After test duration of 150min)



Unless otherwise agreed to writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. As extion is drawn to the limitation of liability, indemnification and invadiction issues defined therein. Any holder of this document is activated that information contained hereon reflects the Company's finance at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is a its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in time without prior written approval of the Company. Any under the in relaction documents. This document cannot be reproduced unauthorized alteration, forgery or falsification of the content or appearance of this unauthorized alteration, forgery or falsification of the content or appearance of this unauthorized alteration, forgery or falsification of the content or appearance of this ocument is unlawful and offenders may be prosecuted st report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No. 301, Sunlight Road, 2 Block, Sunlight Industry Zone, Anji County, Zheijang Province, China 313300 t (86-572) 5018825 f (86-572) 5018829 www.sgsgroup.com.cn 邮编: 313300 t (86-572) 5018825 f (86-572) 5018820 sgs.china@sgs.com 中国・浙江・安吉县阳光工业园二区阳光大道301号

zeldoor.com

COM